



Stepper Motor Specifications:

MODEL	Phase	Step Angle	Rated Voltage	Current /Phase	Resistance /Phase	Inductance /Phase	Holding Torque	Rotor Inertia
		Deg/Step	V	A	Ω	mH	kg.cm	g.cm ²
57STH56	2	0.9	2.52	2.8	0.9	4.5	12	300